Work Order December-17-13	r ID 110063 9:07:21 AM	3535-23	*110	<b>063</b> *						Page 1
Item ID: I Revision ID:	D3535-23	B110663	Accept	*N900	<b>040</b>	100	<b>ን</b> * s	etup Star	17	S1*
Item Name: S	Stainless Steel Wearplate Center F	wd						Stop	, <b>*</b> N	S2*
Start Date: 1 Required Date: 1	12/17/13 Start Qty: 6.00 12/17/13 Req'd Qty: 6.00	<b>``</b>		Cust Item I Customer:	D:			<del>-</del>		
Reference:								<b>62</b> ~		
Approvals:	Process Plan:	Date: 13-12-	// Tooling:	Da	ite:	<u>-</u> 	R	tun Star Stoj	^I <i>\</i> I	R1*
	QC:	Date:	SPC (Y/N):	Da	ıte:				*N	R2*
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr									
D3535	Rev B									
*1 NA* Waterjet FLOW CNC Waterjet		per Dwg D3535 Dwg R f necessary	0.00 ev: <b>B</b> Prog Rev: <b>B</b>	2-			12	_0_		Jm 14-1-
110 *110* QC Quality Control	QC2- Inspect parts o  Memo	ff machine FAI/FAIB	0.00							J <u>m 14-1</u> -c
120 <b>*190*</b> QC Quality Control	QC8- Inspect parts -	second check	0.00 <b>DAS</b> 9 <b>89</b> 0.00 <b>J</b> 4	۵			<u></u>			

Quality Control

Work Order ID 110063  December-17-13 9:07:21 AM			*110063*								Page 2		
Revision ID: Item Name:	12/17/13	l Wearplate Center Fwd  Start Qty: 6.00  Req'd Qty: 6.00	*6* *6*	Accept	*N900 Cust Item Customer:		100	)*	Setup	Start Stop		S1* S2*	===
Approvals:	Process Pla	ın:	Date:	Tooling: SPC (Y/N):		ate:	-		Run	Start Stop	<b>^</b>   <i>\</i>	R1*	
Sequence ID/ Work Center II		Operation Description NC BRAKE		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	t Rej Qty	ject 7	Reject Number	Insp. Stamp	DAS
*120* Brake NC Brake NC		<b>Memo</b> 1-Form on B		0.00 using Jigs DT8261and DT T81583-Identify as D3535		DAS 30 9-89		idx				19/0/19	9-89
140 <b>*140</b> *		QC5- Inspect part comple	teness to step on W/O	0.00 DAS 27 0.00 9-89				12				DAS 34 79-89	<b>/</b>

150

Grey Sandtex(Ref:4.3.5.6) per QSIQ05 4.3

0.00

\*150\* Powdercoat

vdercoat

Memo

0.00

Powder Coating

START TIME: OVEN TEMPERATURE:

12 & 14-1-14.

34

9-89

	ler ID 11000	63		*110				Page 3			
Item ID: Revision ID: Item Name:	D3535-23 Stainless Steel We	arplate Center Fwd		Accept	*N900	<u>ი</u> 4ი	100	<b>)*</b> s	Setup Star	1 1	S1* S2*
Start Date: Required Date Reference:		eq'd Qty: 6.00	*6* *6*		Cust Item I Customer:	D:	_		S		
Approvals:	Process Plan:		Date:	Tooling:	Da	ate:	_	·	Run Sta	^IV	R1*
	QC:		Date:	SPC (Y/N):	Da	ate:			Sto	, *V	R2*
Sequence ID/ Work Center	-	peration escription		Set Up/ Run Højsss	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
*160 *160*	QC	C3- Inspect Part Finish		0.00 <b>27</b>				12			-
QC Quality Control		Memo		0.00 14[1]	S						
170	Ide	entify as per dwg & Sto	ck Location: FP	- OO 0.00					ſ	n. ()	1 .
*170* Packaging Packaging		Мето	,	0.00				117	<u> </u>	<u> </u>	Mode

180

QC21- Final Inspection - Work Order Release

0.00

<u>\*</u>1ጸበ\*

QC Quality Control

Memo

0.00

# 14-01-15 14-01-15 December-17-13 9:07:21 AM

Work Order ID:

110063

**Parent Item:** 

D3535-23

Parent Item Name:

Stainless Steel Wearplate Center Fwd

**Start Date:** 12/17/13

Required Date: 12/17/13

Start Qty: 6.00

Required Qty: 6.00

**Comments:** 

IPP Rev:A New Issue 07-02-15 JLM

IPP Rev:B As per Rev B 07-08-31 JLM Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S20GA		Purchased	No		·	100	sf	436.3000	1.3615	8.598947	4_		<u> </u>
304/316 .040 Sheet											19		Jm 14-
				<b>Location</b>		Loc Oty	Lo	c Code					
				MAT020		436.30001							
				m12	5754	24.17001							
				m12	6852	111.13			****				
				m12	7454	301			127	1 <u>54</u>			

NCR: Y	es / No				WORK ORDER NON-C	CON	NFORM	MANCE / UP	DATE	•		
										QA Closed:	Date:	;
Work Orde	ır.				DISPOSITION				AGAINST DE	PARTMENT	PROCESS	
Part No.			Rework Scrap Use-as-is		ſ	Skid-tube Machining noforming	Crosstube Small Fab Finishing	Water Jei Prod. Eng. Coor Rec/Store/Packaging		Engineering Quality Other		
NCR N	o			<del></del>	Work Order Update							
Root				Descri	ption of work order update		nitial	Ac	tion	Sign &		
Cause	Date	Step	Qty	(	or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data												
Equip/Tooling												
Operator		Ì										
Material												
Setup												
Other		l										
Process	_											
Supplier	_											
Training	_											
Unapproved										:		
						AUL	T CATE	GORY				
Landin	ng Gear				General	_	1		_	7		7
]_	Bending			<u> </u>	Bend		Grain			Ovalized		Pressure/Forced
ļ	Centre N	ot Conce	ntric to	o/s	BOM/Route		Hardwa	re		Over/Under	tolerance	Temperature/Cure
	Cracks				Broken/Damaged	Ш	Inspecti	on incomplete		Part Incorred	it	Weld
	Crushed/	'Crimped			Burrs		Instruct	ions Incomplete/	Unclear	Part Lost/Mi	ssing	Wrong Stock Pulled
	Cuffs				Contamination		Mainte			Part Moved		
	Heat Trea	at			Countersink		Mislabe	led		Positioned V		<b>-</b>
	Inspectio	n Strip in	Tube		Cut Too Short		Misread	1		Power Loss/	Surge	Other
	Ripples in	n Bend			Drill Holes		Offset					
Í	Torque Waves in Extrusion		Drawing	Out of Calibration								

Out of Sequence

Outside Dimensions

DQA:

Date:

Turning Sequence

Wave/Twist in Tube

Finish

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

DART AEROSPACE LTD	Work Order:	110063
Description: Wearshoe	Part Number:	D3535-23
Inspection Dwg: D3535 Rev: B		Page 1 of 1


## FIRST ARTICLE INSPECTION CHECKLIST

X Fi	irst Article		Prototype
------	--------------	--	-----------

Drawing		Actual			Method of	0
Dimension	Tolerance	Dimension	Accept	Reject	Inspection	Comments
1.885	+/-0.010	1.895"			٧	Jkmol
2.000	+/-0.010	2.000"			٧	
4.750	+/-0.010	4.750"	_		V	
9.500	+/-0.010	9,500"	_		· T	Thmolo
14.250	+/-0.010	14,250"			<b>+</b>	
17.750	+/-0.010	17.750	_		T	
23.140	+/-0.010	23.140			T	
28.530	+/-0.010	28-530"	_	,	+	
33.920	+/-0.010	33.920~			Т	
39.310	+/-0.010	39.310"			τ .	_
44.700	+/-0.010	44.705°			Τ	
48.200	+/-0.010	48.200"	_		۲	
52.850	+/-0.010	52.850"			T	
Ø0.188	+0.005/-0.001	0.190"	)		V	
48.00	+/-0.030	4800°	Į.		1	
39.00	+/-0.030	39.00"	-		۲	
32.00	+/-0.030	32.000	_		T	
24.00	+/-0.030	24.00°	_		†	
16.00	+/-0.030	16.00°	<u> </u>		. +	
8.00	+/-0.030	8.005			٧	
6.00	+/-0.030	6.003"	_		V	·
0.300	+/-0.010	o.303°	_		V ,	
0.300	+/-0.010	0.302"	_		ν	
0.038	+/-0.010	- A 3 - "	DAS		V	

		27		
Measured by: Jm	Audited by:	9-89	Prototype Approval:	N/A
Date: 14-1-9	Date:	14/1/10	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	07.11.23	New Issue	KJ/EC/DD	<i>M</i>



봀 DOCUMENT ß Copyright © 2006 by DART AEROSPACE USA, INC.

PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC. 유 COPIED

07.04.17

WEARSHOE

ME

CHECKED


APPROVED

B

3

42.40.La

RELEASE





D3535-31 BEND DETAIL

110063

24.500
21.000
15.250
9.500
2.000
Q
6.00 - 6.75 - DETAIL A
1.885 — 1   1   1   1   1   1   1   1   1   1
(TYP 3 PLS)
N3535—33F FLAT PATTERN

<u>UJJJJ-JJP PLAL PALIERN</u>

c-	_	_	
c-			
D353	5-33 BEND	DETAIL	

1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524, 20 GAUGE (0.038 THICK) (REF DART SPEC M304S20GA)
2) FINISH: POWDER COAT GREY SANDTEX (4.3.5.6) PER QSI 005 4.3

3) PART IS SYMMETRICAL ABOUT ©
4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

5) ALL DIMENSIONS ARE IN INCHES

BREAK ALL SHARP EDGES TO 0.010 MAX

IDENTIFY WITH DART P/N USING WHITE FINE POINT PAINT MARKER

8) SEE PAGE 7 FOR DETAILS AND SECTION

Copyright © 2006 by DART AEROSPACE USA, INC.

PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

PURPOSE

유

COPIED

뒾

DOCUMENT IS

D3535 DRAWING NO. DART **AEROSPACE** PORT HADLOCK, JSA, SHEET RC.

**♣** 0F

SCALE 1:10

REV.

Section 1.						Á
						en a
szid						
Ţ		-				1
•						
						- dia
						di e
p) Terr						ا مام
						المائلة
A CONTRACTOR OF THE CONTRACTOR						
						un e
			7			iliya da j
						A
						14.
	The second secon	2 (20) (20) (20) (20) (20) (20) (20) (20		William Conference State Conference Conferen	1. の機能の対象を対象を対象を対象を対象を対象を対象を対象を対象を対象を対象を対象を対象を対	
<b>P</b>	ust ut					i.
-						•
						1
an errore						



CHECKED

D3535

SHEET

5 OF

SCALE

R.

B

DART

AEROSPACE PORT HADLOCK,

USA,


NC.

DATE

07.04.17

42.40.64

THE POSE



## D3535-35F FLAT PATTERN

9.500

4.750

2.000

1.885




110063

27.250 ————————————————————————————————————	
2.000 4.750 DETAIL A  D3535-37F FLAT PATTERN  D3535-37F FLAT PATTERN  D3535-37F FLAT PATTERN	WEARSHOE

1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524,
20 GAUGE (0.038 THICK)
(REF DART SPEC M304S20GA)
2) FINISH: POWDER COAT GREY SANDTEX (4.3.5.6) PER
QSI 005 4.3
3) PART IS SYMMETRICAL ABOUT 
4) TOLERANCES ARE PER DART QSI 018 UNLESS
OTHERWISE NOTED
5) ALL DIMENSIONS ARE IN INCHES

- ALL DIMENSIONS ARE IN INCHES
- BREAK ALL SHARP EDGES TO 0.010 MAX
- IDENTIFY WITH DART P/N USING WHITE FINE POINT PAINT MARKER
- 8) SEE PAGE 7 FOR DETAILS AND SECTION



봀

Copyright @ 2006 by DART AEROSPACE USA, INC.

DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC. **PURPOSE** 유

COPIED

		·		
	<b>6.</b>			
			•	
			•	
				199 1
				1
				1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
				. 9
6				